

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
01	001	007	0000000043	7022.0250 - 7022.0480	Protection	A12FA 250V	
01	001	007	0000000043	7022.0000 - 7022.0220	Protection	A12FA 380V	
01	001	007	0000000043	7022.0500 - 7022.0710	Protection	A12FA 500V	
01	001	007	0000000043	7022.0750 - 7022.0880	Protection	A12FA 660V	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

## 2 Type of change

Internal testing regarding non fusing time

## 3 Detailed description of change

The non fusing time 60 minutes is done at 1.1\*In instead of 1.5\*In

## 4 Reason of change

Improvement of product quality

## 5 Released date

Week 15/2010

## 6 Impact of change and recommended action

## 7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Datasheet:	<b>A12FA 250V</b>	Part list: from 7022.0250 up to 7022.0480
Datasheet:	<b>A12FA 380V</b>	Part list: from 7022.0000 up to 7022.0220
Datasheet:	<b>A12FA 500V</b>	Part list: from 7022.0500 up to 7022.0710
Datasheet:	<b>A12FA 660V</b>	Part list: from 7022.0750 up to 7022.0880

<b>A12FA 250V 380V 500V 660V</b>					<b>0734</b>	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
2010 April 08	JMK	2010 April 12	JMK	<b>002. 0001</b>	<b>a</b>	1 von 1