

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	063	0000000686	0031.2320	Circuit protection	FUL fuse carrier 6.3x32 IP67	n/a
				0031.2322		FUL fuse carrier 5x20 IP67	n/a
			0000000602	0031.2321		FUL fuse carrier 6.3x32 IP40	n/a
				0031.2323		FUL fuse carrier 5x20 IP40	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

- Change of material for 5x20mm and 6.3x32mm fuse carrier
- Improved holding spring for 6.3x32mm fuse carrier

3 Detailed description of change

New plastic material without change on function or appearance.

New holding spring for 6.3x32mm fuse carrier 0031.2320 and 0031.2321



4 Reason of change

- Product improvement to fulfil the enhanced glow wire requirements according to the updated standard IEC 60127-6 and the standard IEC 60335-1 for appliances in unattended use.

5 Release date

The change will be rolled-out starting ww 50/2016 (Date code 1650 or higher on label) and lasts approx. 3 months depending on the variant.

6 Impact of change and recommended action

Form	Yes	Change plastic material for 5x20mm and 6.3x32mm fuse carrier New holding spring for 6.3x32mm fuse carrier
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet	Fuse carrier IP67
Data sheet	Fuse carrier IP40

Product Change Notification					Product improvement fuse carrier FUL		
owner	creation date	release date	released by	change order no	rev	page	D10-010-239
dislercy	2016-10-27	2016-11-02	nowakfr	2011357	A	1 of 1	