

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	007	022	0000002056	GSP2.XXXX.XX	Connectors	GSP2	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Modification of Approval marks

3 Detailed description of change

SEMKO and SEV approvals for GSP2 expired since 2006. Both marks are removed and the new CCC approval mark is on the GSP2 body.

Old marking:



NEW marking



GSP2					0118.2044	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
26.08.2010 15:30:34	SHA	02.11.2010	SHA	21642	-	1 von 2

4 Reason of change

Chinese approval

5 Released date

Release for series production

Ww44/2010

6 Impact of change and recommended action

Form: New Approval
Fit: N/A
Function: N/A
Production Site: Change of tool
Product label: N/A

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
CRM	300009424	
Notification of change	21642	

GSP2					0118.2044	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
26.08.2010 15:30:34	SHA	02.11.2010	SHA	21642	-	2 von 2