

1 Products affected:

All KG and CG power entry modules KGXX.XXXX.XXX
CGXX.XXXX.XXX


2 Type of change :

Socket and filtercase modification


3 Detailed description of change:

KG : Reinforcement between inlet and switch
CG : Filtercase is made in one piece

Existing design



New design



4 Reason of change:

Improved evenness of socket-flange

5 Released date:

Production released	KG 0817	
Production released	CG 0824	

6 Impact of change and recommended action:

Form : see no. 3
Fit : N/A
Function : N/A

7 Reference Documents / Attachments:

Kind of document	Document number	Remark
Notification of change	19346	Not attached

KG/CG					0118.2009	
Created date:	Created by:	Released date:	Released by:	Notification-Nr.	Index	Page
19.02.2008 14:01:41	HOL	07.07.2008	HOL	19884	a	1 of 1