

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	002	0000002321	See list below	Connectors	1061 Appliance inlet

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected							
6162.0003	6162.0004	6162.0005	6162.0006	6162.0007	6162.0008	6162.0009	6162.0010
6162.0011	6162.0118	6162.0120	6162.0135	6162.0160	6162.0169		

2 Type of change

- Standards update and modification of approval marks.

3 Detailed description of change

Old product appearance 1061 PC I	New product appearance PC I
Old product appearance 1061 PC II	New product appearance PC II
Old product approval	New product approval
UL and CSA mark	Combined UL/CSA approval according to UL 60320-1
Old label	New Label

4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Released date

The change will be rolled-out starting ww 07/2018 and lasts approx. 6 months depending on the variant. Products manufactured before as well as after this date still have a valid approval certificate.

Engineering Documentation					PCN 1061 Appliance Inlet		
owner	creation date	release date	released by	change order no	rev	page	D10-025-023
lokhanze	25.04.2018	08.11.2018	limachcl	2016052	A	1 of 2	

6 Impact of change and recommended action

Form	Yes	Replacement of UR and cCSAus mark with combined cURus mark.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Replacement of UR and cCSAus mark with combined cURus mark.
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data Sheet 1061		

Engineering Documentation					PCN 1061 Appliance Inlet		
owner	creation date	release date	released by	change order no	rev	page	D10-025-023
lokhanze	25.04.2018	08.11.2018	limachcl	2016052	A	2 of 2	