

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type/ Description	Customer part no.
SBU	PG	PGU	Type				
01	002	002	0000000500	3101.0010/.0015/.0110/.0115/.0210/.0215/0310/.0315	Protection	FPG 1	
01	002	002	0000000501	3101.0020/.0025/.0120/.0125/.0220/.0225/0320/.0325	Protection	FPG 2	
01	001	002	0000000502	3101.0030/.0031/.0035/.0036/.0230/.0331/0235/.0336	Protection	FPG 3	
01	001	002	0000000506	3101.0060/.0160/.0161/.0260	Protection	FPG 6	

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

## 2 Type of change

New Korean approval mark

## 3 Detailed description of change

All documents with the old Korean approval mark changed to the new Korean mark.  
Only the label on the packing has changed.

## 4 Reason of change

For marketing purpose the Korean testing laboratory changed the layout of its approval mark

## 5 Released date

Immediately

## 6 Impact of change and recommended action

Form: Approval mark on the Label  
Fit: N/A  
Function: N/A  
Production Site: New Tools

## 7 Reference Documents / Attachments

Kind of document	Document number	Remarks
Data sheet	0105.1320	
Engineering specification	0109.0036	

FPG 1, FPG 2, FPG 3, FPG 6					0118.2060	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
19.01.2011 12:45:43	HRÜ	04.03.2011	HRÜ	21206	-	1 von 1